

Contact Records Index

Additional files/attachments/figures supporting some contact records are available on the Contact Records webpage.

CR 2009-01	Phase II and III Upgrades to Solar Ponds Plume Treatment System
CR 2008-09	Revision of sampling locations to reflect Site reconfiguration
CR 2008-08	Construction of collection sump for SPPTS
CR 2008-07	Path forward for Original Landfill (OLF) Seep 7 drain extension, berm maintenance and repair, perimeter channel slope cut and fill, and modification of the OLF Monitoring and Maintenance Plan (M&M Plan).
CR 2008-06	Management of intercepted groundwater during SPPTS repair or maintenance activities
CR 2008-05	Boron and uranium in groundwater downgradient of the Original Landfill
CR 2008-04	Notification of well replacement and well identification change
CR 2008-03	Exploratory excavations to greater than 3 feet below grade generally between the former Interceptor Trench Pump House and Solar Ponds Plume Treatment System
CR 2008-02	Discussion and approval of excavation greater than 3 feet below grade to breach dams A-1, A-2, B-1, B-2, B-3, and B-4
CR 2008-01	Completion of additional ecological sampling in accordance with RFLMA Attachment 2, Table 5
CR 2007-08	Changes to Present Landfill inspection and monitoring frequencies and modification of the PLF Monitoring and Maintenance Plan
CR 2007-07	Replacement of monitoring well 45605 (B991 slump)
CR 2007-06	Evaluation of elevated nitrate in groundwater samples from AOC well B206989
CR 2007-05	Grading the slump area south of FC-4 and former Building 991
CR 2007-04	Discussion and approval of soil disturbance for Phase III road improvement work involving the construction of roadside drainage ditches that will not return excavation to preexisting grade
CR 2007-03	Discussion and approval of excavation greater than 3 feet below grade in FC-1 soil borrow area and placement of soil south of former B371 location to eliminate ponding around well heads for wells 33502, 33604, and 33703
CR 2007-02	Discussion and approval of exploratory excavations to greater than 3 feet below grade around the former Interceptor Trench Pump House

Contact Records Index

Additional files/attachments/figures supporting some contact records are available on the Contact Records webpage.

- CR 2007-01 Notification of adverse biological condition, March 27, 2007, Central Operable Unit (COU) boundary fence wildlife deaths
- CR 2006-03 Disposition February–July 2006 monitoring results for arsenic at the Present Landfill Treatment System (PLFTS).
- CR 2006-02 Disposition December–July 2006 monitoring results for boron at the Present Landfill Treatment System (PLFTS)
- CR 2006-01 Disposition December 2005–May 2006 monitoring results for manganese at the Present Landfill Treatment System (PLFTS)